Exploring rpvst_to_pvst.pcapng

SW4	Cisco PVST+	STP Multicast	SW3
Gi1			Gi1

📁 **rpvst_to_pvst.pcapng**

⚠️ RSTP Topology Change — Frame 1 | 2020-05-01T20:35:32.476515Z

Root Path Cost	0
Port identifier	0x8006

⚠️ RSTP Topology Change — Frame 2 | 2020-05-01T20:35:32.476537Z

Root Path Cost	0
Port identifier	0x8006

⚠️ RSTP Topology Change — Frame 3 | 2020-05-01T20:35:32.476771Z

Root Path Cost	0
Port identifier	0x8006

⚠️ RSTP Topology Change — Frame 4 | 2020-05-01T20:35:32.476919Z

Root Path Cost	0
Port identifier	0x8006

⚠️ RSTP Topology Change — Frame 5 | 2020-05-01T20:35:32.477105Z

Root Path Cost	0
Port identifier	0x8006

⚠️ RSTP Topology Change — Frame 6 | 2020-05-01T20:35:32.477843Z

Root Path Cost	0
Port identifier	0x8006

📋 RSTP Proposal — Frame 7 | 2020-05-01T20:35:32.479241Z

Forwarding	No
Learning	No
🔌 Port Role	Designated (3)
Root Path Cost	100
Port identifier	0x8006

📋 RSTP Proposal — Frame 8 | 2020-05-01T20:35:32.479366Z

Forwarding	No
Learning	No
🔌 Port Role	Designated (3)
Root Path Cost	100
Port identifier	0x8006

⚠️ RSTP Topology Change — Frame 9 | 2020-05-01T20:35:32.479395Z

Root Path Cost	0
Port identifier	0x8006

📋 RSTP Proposal — Frame 10 | 2020-05-01T20:35:32.47946Z

Forwarding	No
Learning	No
🔌 Port Role	Designated (3)
Root Path Cost	100
Port identifier	0x8006

📋 RSTP Proposal — Frame 11 | 2020-05-01T20:35:32.479493Z

Forwarding	No
Learning	No
🔌 Port Role	Designated (3)
Root Path Cost	100
Port identifier	0x8006

📋 RSTP Proposal — Frame 12 | 2020-05-01T20:35:32.479541Z

Forwarding	No
Learning	No
🔌 Port Role	Designated (3)
Root Path Cost	100
Port identifier	0x8006

📋 RSTP Proposal — Frame 13 | 2020-05-01T20:35:32.479611Z

SW4 | Gi1 | Cisco PVST+ | STP Multicast | SW3 | Gi1

Forwarding	No
Learning	No
Port Role	Designated (3)
Root Path Cost	100
Port identifier	0x8006

RSTP Proposal — Frame 14 | 2020-05-01T20:35:32.479641Z

Forwarding	No
Learning	No
Port Role	Designated (3)
Root Path Cost	100
Port identifier	0x8006

RSTP Topology Change — Frame 15 | 2020-05-01T20:35:34.482426Z

Root Path Cost	0
Port identifier	0x8006

RSTP Topology Change — Frame 16 | 2020-05-01T20:35:34.482509Z

Root Path Cost	0
Port identifier	0x8006

RSTP Topology Change — Frame 17 | 2020-05-01T20:35:34.485925Z

Root Path Cost	0
Port identifier	0x8006

RSTP Topology Change — Frame 18 | 2020-05-01T20:35:34.486772Z

Root Path Cost	0
Port identifier	0x8006

RSTP Topology Change — Frame 19 | 2020-05-01T20:35:34.486796Z

Root Path Cost	0
Port identifier	0x8006

RSTP Topology Change — Frame 20 | 2020-05-01T20:35:34.486802Z

Root Path Cost	0
Port identifier	0x8006

RSTP Topology Change — Frame 21 | 2020-05-01T20:35:34.486807Z

Root Path Cost	0
Port identifier	0x8006

RSTP Topology Change — Frame 22 | 2020-05-01T20:35:38.117437Z

Root Path Cost	100
Port identifier	0x8006

RSTP Topology Change — Frame 23 | 2020-05-01T20:35:38.117477Z

Root Path Cost	100
Port identifier	0x8006

RSTP Topology Change — Frame 24 | 2020-05-01T20:35:38.213545Z

Root Path Cost	100
Port identifier	0x8006

RSTP Topology Change — Frame 25 | 2020-05-01T20:35:38.213607Z

Root Path Cost	100
Port identifier	0x8006

RSTP Topology Change — Frame 26 | 2020-05-01T20:35:38.238975Z

Root Path Cost	100
Port identifier	0x8006

RSTP Topology Change — Frame 27 | 2020-05-01T20:35:38.239009Z

Root Path Cost	100
Port identifier	0x8006

RSTP Topology Change — Frame 28 | 2020-05-01T20:35:38.23995Z

Root Path Cost	100
Port identifier	0x8006