





rpvst_topo_change.pcapng









SW3

Cisco PVST+

STP Multicast

SW1 (Root Bridge)

Root Path Cost	0
Port identifier	0x8001

RSTP Forwarding

Port Role	Designated (3)
Root Path Cost	0
Port identifier	0x8001

Frame 44 |
2020-05-01T20:29:59.629286Z

RSTP Forwarding

Port Role	Designated (3)
Root Path Cost	0
Port identifier	0x8001

Frame 45 |
2020-05-01T20:29:59.648499Z

RSTP Forwarding

Port Role	Designated (3)
Root Path Cost	0
Port identifier	0x8001

Frame 46 |
2020-05-01T20:29:59.649255Z

RSTP Forwarding

Port Role	Designated (3)
Root Path Cost	0
Port identifier	0x8001

Frame 47 |
2020-05-01T20:29:59.649718Z

RSTP Forwarding

Port Role	Designated (3)
Root Path Cost	0
Port identifier	0x8001

Frame 48 |
2020-05-01T20:29:59.650126Z

RSTP Forwarding

Port Role	Designated (3)
Root Path Cost	0
Port identifier	0x8001

Frame 49 |
2020-05-01T20:29:59.65051Z